
The Trail Inventory of Muleshoe NWR

Muleshoe, TX





Prepared By: Federal Highway Administration Central Federal Lands Highway Division February, 2012



TABLE OF CONTENTS

<u>SECTION</u>		<u>PAGE</u>
I.	TRAIL AND TRAIL FEATURE SUMMARIES	1 - 1
II.	TRAIL LOCATION MAPS	2 - 1
III.	TRAIL IDENTIFICATION LIST	3 - 1
IV.	TRAIL CONDITION RATING SHEETS	4 - 1
V.	TRAIL DEFICIENCY RATING SHEETS	5 - 1
VI.	PHOTOGRAPHIC SHEETS	6 - 1
VII.	GLOSSARY	i

Muleshoe NWR

Trail and Trail Feature Summaries

Trail Miles and Percentages by Surface Type and Condition

Trail Surface	Excellent		Good		Poor		Total
Type	Miles	%	Miles	%	Miles	%	Miles
Native	0.84	76%	0.06	5%	0.21	19%	1.11
Mowed	0.10	100%	0.00	0%	0.00	0%	0.10
Total	0.94	78%	0.06	5%	0.21	17%	1.21

Trail Miles and Percentages by Trail Classification and Condition

Trail	Excell	ent	nt Good		Poor		Total
Classification	Miles	%	Miles	%	Miles	%	Miles
TC2	0.94	78%	0.06	5%	0.21	17%	1.21
Total	0.94	78%	0.06	5%	0.21	17%	1.21

^{*}Admin Roads are included in the inventory but are not rated for condition.

Trail Features

Trail Number	Feature Type	Quantity	Grouped Feature	Milepost	Photo
T200	Sign	1	No	0.00	MULE_C2_088
T200	Trailhead	1	No	0.00	MULE_C2_088 4
T200	Step: Log -each	5	No	0.01	
T200	Sign	1	No	0.03	MULE_C2_088 5
T200	Bench	1	No	0.19	
T200	Bridge -sf	54	No	0.19	MULE_C2_088
T200	Begin Section	1	No	0.31	MULE_C2_090 3
T200	Sign	1	No	0.43	MULE_C2_088 7
T200	Begin Section	1	No	0.43	MULE_C2_090 4
T200	Bridge -sf	32	No	0.43	MULE_C2_090 4
T200	Sign	1	No	0.45	MULE_C2_088
T200	Bench	1	No	0.46	
T200	Sign	1	No	0.47	MULE_C2_088
T200	Sign	1	No	0.49	MULE_C2_089
T200	Sign	1	No	0.53	MULE_C2_089
T200	Sign	1	No	0.56	MULE_C2_089
T200	Sign	1	No	0.60	MULE_C2_089
T200	Sign	1	No	0.61	MULE_C2_089 4
T200	Sign	1	No	0.62	MULE_C2_089 5
T200	Sign	1	No	0.64	MULE_C2_089
T200	Sign	1	No	0.65	MULE_C2_089 7
T200	Sign	1	No	0.68	MULE_C2_089
T200	Sign	1	No	0.73	MULE_C2_089
T200	Begin Section	1	No	0.76	MULE_C2_090 2

T200	Sign	1	No	0.76	MULE_C2_089
					9
T200	Bench	1	No	0.78	
T201	Sign	1	No	0.00	MULE_C2_090 5
T201	Trailhead	1	No	0.00	MULE_C2_090 5
T201	Bridge -sf	126	No	0.08	MULE_C2_090 6
T201	Bench	1	No	0.21	

sf - square feet If - linear feet


cf - cubic feet

Muleshoe NWR Trail Location Map










Trails ID

Station Name: Muleshoe NWR Org Code: 21590

Trail Number	Trail Name	Surface Type	SAMMS	Trail Mileage	Trail Description (Begin and End point of trail)
T200	Swamp Trail	Mowed	10047129	0.10	From Camping Loop Road (Rte 100) to End
T200	Swamp Trail	Native	10047129	0.90	From Camping Loop Road (Rte 100) to End
T201	Paul's Lake Trail	Native	10047129	0.21	From Paul's Lake Parking Area (Rte 904) to End

TRAIL CONDITION






Trail Name:Swamp TrailRefuge Name:Muleshoe NWRTrail Number:T200Region: 2Total Length:1.00 Miles

Section Number	001	002	003	004
Section Length (miles)	0.79	0.10	0.06	0.05
SAMMS Number	10047129	10047129	10047129	10047129
Rating Date	05/10/2006	05/10/2006	05/10/2006	05/10/2006
Trail Section Information				
Trail Class	TC2	TC2	TC2	TC2
Surface Type	Native	Mowed	Native	Native
Surface Firmness	Firm	Firm	Firm	Firm
Width (inches)	120	120	120	24
Average Grade (%)	2.9	2.9	2.9	2.9
Average X-slope (%)	4.40	4.40	4.40	4.40
Trail Condition Information				
Deferred Maintenance			\$791	
CRV	\$151,965	\$4,809	\$11,542	\$1,924
FCI	0.00	0.00	0.05	0.00
Condition	Excellent	Excellent	Good	Excellent

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
\$791	\$170,240	0.00	Excellent

TRAIL CONDITION



Trail Name:Paul's Lake TrailRefuge Name:Muleshoe NWRTrail Number:T201Region: 2Total Length:0.21 Miles

I .	
Section Number	001
Section Length (miles)	0.21
SAMMS Number	10047129
Rating Date	05/10/2006
Trail Section Information	
Trail Class	TC2
Surface Type	Native
Surface Firmness	Firm
Width (inches)	108
Average Grade (%)	1.5
Average X-slope (%)	2.10
Trail Condition Information	
Deferred Maintenance	\$7,457
CRV	\$36,355
FCI	0.15
Condition	Poor

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
\$7,457	\$36,355	0.15	Poor

TRAIL DEFICIENCY




Trail Name:Swamp TrailRefuge Name:Muleshoe NWRTrail Number:T200Region: 2

Mile Post	0.43
Section Number	003
Photo Number	MULE_C2_0904
Deficiency	Trail Structure
Action	Repair
Item	Bridge -sf
Quantity	32
Deferred Maintenance	\$791

Total Length: 1.00 Miles

TRAIL DEFICIENCY



Trail Name: Paul's Lake Trail Refuge Name: Muleshoe NWR **Trail Number:** T201 Region: 2

0.08 Mile Post 001 Section Number Photo Number MULE_C2_0906 Trail Structure Deficiency Replace Action Bridge -sf Item Quantity 126 **Deferred Maintenance** \$7,457

Total Length: 0.21 Miles

TRAIL NUMBER: T200 STATION: Muleshoe NWR

DATE: 05/10/2006



Photo # MULE_C2_0884 - MP 0.00 - Trailhead

TRAIL NUMBER: T200 STATION: Muleshoe NWR



Photo # MULE_C2_0883 - MP 0.00 - Sign

TRAIL NUMBER: T200 STATION: Muleshoe NWR

DATE: 05/10/2006



Photo # MULE_C2_0885 - MP 0.03 - Sign



Photo # MULE_C2_0886 - MP 0.19 - Bridge -sf

TRAIL NUMBER: T200 STATION: Muleshoe NWR DATE: 05/10/2006



Photo # MULE_C2_0887 - MP 0.43 - Sign



Photo # MULE_C2_0888 - MP 0.45 - Sign

TRAIL NUMBER: T200 STATION: Muleshoe NWR DATE: 05/10/2006



Photo # MULE_C2_0889 - MP 0.47 - Sign



Photo # MULE_C2_0890 - MP 0.49 - Sign

TRAIL NUMBER: T200 STATION: Muleshoe NWR DATE: 05/10/2006



Photo # MULE_C2_0891 - MP 0.53 - Sign

TRAIL NUMBER: T200 STATION: Muleshoe NWR



Photo # MULE_C2_0892 - MP 0.56 - Sign

TRAIL NUMBER: T200 STATION: Muleshoe NWR

DATE: 05/10/2006



Photo # MULE_C2_0893 - MP 0.60 - Sign



Photo # MULE_C2_0894 - MP 0.61 - Sign

TRAIL NUMBER: T200 STATION: Muleshoe NWR DATE: 05/10/2006



Photo # MULE_C2_0895 - MP 0.62 - Sign

TRAIL NUMBER: T200 STATION: Muleshoe NWR



Photo # MULE_C2_0896 - MP 0.64 - Sign

TRAIL NUMBER: T200 STATION: Muleshoe NWR DATE: 05/10/2006



Photo # MULE_C2_0897 - MP 0.65 - Sign

TRAIL NUMBER: T200 STATION: Muleshoe NWR



Photo # MULE_C2_0898 - MP 0.68 - Sign

TRAIL NUMBER: T200 STATION: Muleshoe NWR DATE: 05/10/2006



Photo # MULE_C2_0899 - MP 0.73 - Sign



Photo # MULE_C2_0899 - MP 0.76 - Sign

TRAIL NUMBER: T200 STATION: Muleshoe NWR

DATE: 05/10/2006



Photo # MULE_C2_0903 - MP 0.31 - Begin Section

TRAIL NUMBER: T200 STATION: Muleshoe NWR



Photo # MULE_C2_0904 - MP 0.43 - Begin Section

TRAIL NUMBER: T200 STATION: Muleshoe NWR

DATE: 05/10/2006



Photo # MULE_C2_0904 - MP 0.43 - Bridge -sf

TRAIL NUMBER: T200 STATION: Muleshoe NWR



Photo # MULE_C2_0902 - MP 0.76 - Begin Section

TRAIL NUMBER: T201 STATION: Muleshoe NWR

DATE: 05/10/2006



Photo # MULE_C2_0905 - MP 0.00 - Trailhead

TRAIL NUMBER: T201 STATION: Muleshoe NWR



Photo # MULE_C2_0905 - MP 0.00 - Sign

TRAIL NUMBER: T201 STATION: Muleshoe NWR



Photo # MULE_C2_0906 - MP 0.08 - Bridge -sf

Glossary of Terms and Abbreviations

Acc Info Accessibility information available at trailhead.

Action Action required to correct deficiency.

Admin Road Administration Road. Admin Roads signed and

advertised as trails are included in the trail inventory but

a condition assessment is NOT done.

Alt SAMMS SAMMS number of Alternate Facility Type.

Alt Type Alternate Facility Type. Trail lies on a feature such as a

levee, dam, administrative road or bridge, which has a

separate SAMMS number.

AvgGrade The average grade of the trail (%). The average of five

measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.

AvgSlope The average cross-slope of the trail (%). The average of

five measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.

Check Dam A small dam constructed across a drainage ditch, swale,

or channel to lower the speed of concentrated flows.

Condition Subjective rating of trail based on Facility Condition

Index (FCI):

FCI </= - .01 = Excellent FCI .02 - .05 = Good FCI .06 - .10 = Fair FCI .11 - .20 = Poor FCI > - .20 = Failed

Crib Wall Retaining wall.

Current

Replacement Value

(CRV)

The value of an asset determined by the estimated cost of

replacing it.

Def type Deficiency Type: Trail Structure, Drainage, Erosion,

Obstacle, Trail Location, Other.

Deferred

Maintenance (DM)

Maintenance that was not performed when scheduled.

i

Elem ID Unique identifier for each trail section: Org Code-Trail

Number-Section Number.

Facility

Condition Index (FCI)

DM/CRV

Grouped Features Grouped features include non-unique signs (mileposts,

interpretive signs, species identification, etc.), water bars, check dams, steps, drain and drainage dips. For any given grouped feature, a GPS point and photo are taken for the first occurrence only and the total number of features in the group are entered into the "quantity"

field of the data dictionary.

Info Type Type of accessibility information available at trailhead:

brochure, sign or other.

Item Item on which the "Action" (see above) will be

performed.

Manage_Use Managed use of the trail: HIKE, BIKE, NSPC (non-

specified), PACK, POR (portage), SNOWSHOE, XSKI

(cross-country ski), OTHER.

MP Distance of a trail feature or deficiency from the

Trailhead.

Puncheon Log footbridge used in area of poor drainage.

Raised Trail Structure Boardwalk, Turnpike, Puncheon.

T Class Trail Class: I-V (see Appendix? for trail class

descriptions).

Tr Desig Trail Designation: Standard (Std), National Historic Trail

(NHT), National Recreation Trail (NRT), National

Scenic Trail (NST).

Turnpike Trail tread elevated with dirt, rock or other aggregate

from parallel side ditches and held in place by logs.